

Department of Education
Sanathmi Bhaktapur

School Building Preliminary Damage Assessment Data Community School updated May 26, 2015 (updating going on)

SN	Name of District	As per DOE Flash Report					Total number of affected schools	Damaged Facilities (Classroom, ECD, Toilets, Boundary wall, WS)						DEO Building	Teachers Died	Students Died	Remarks	Required TLC
		Number of schools	Number of teachers	Number of students	Number of buildings	Number of classrooms		Fully damaged classrooms	Major damaged classrooms	Minor damaged classrooms	Toilets	Component wall	Water Supply					
Mostly affected 14 Districts																		
1	Kavre	594	3144	102291	1678	6159	548	904	924	1506	52	34	22		25			
2	Sindhupalchok	557	2356	76238	1588	4962	546	2746	1273	909	428			Crack minor: 26	101	19 RC building damage	1270	
3	Dolakha	396	1771	50489	865	4185	363	1632	864	598	99	363	128	collaps	5		115	
4	Bhaktapur	126	1411	34608	389	1717	137	159	180	328	40		35					
5	Kathmandu	299	4194	161795	673	3604	187	448	586	743	43	27	13					
6	lalitpur	200	1870	75588	602	2454	149	303	477		151	53		Crack major				
7	Ramechhap	469	1832	67875	1255	5101	151	581		1186	148		8					
8	Nuwakot	485	2077	79463	1951	5188	485	2622	823	807	378	133	325	Crack red flag	8	Feeder Hostel 1, ETC building damage 1-73 student verified	1624	
9	Rasuwa	98	511	12314	236	1020	98	635	13	98	212		58	Crack	1	1 school administrative Staff	160	
10	Dhading	608	2491	105177	1428	5894	587	2140	946	908	280	95	230		5	9 Based on 587 school out of 608		
11	Gorkha	495	2528	82822	1323	5375	495	2975	99	1187	473	498	498	Crack Major	5			
12	Makwanpur	533	2645	113091	1517	5572	361	383	461	969	87	32	103		5	RC building minor damage/RED	164	
13	Sindhuli	557	2225	107086	1480	6076	451	303	625	1310	84	17	31				328	
14	Okhaldhunga	331	1527	49208	968	3491	228	539	355	510	68		3					
out of 14, Major affected Districts		5748	30582	1112045	15353	60798	4786	16370	7626	11059	2543	1327	1512		45	479		
15	Lamjung	377	2003	47191	1095	3466	197	423	167	285	60	23	2	Simple crack				
16	Syangja	544	2999	78870	1710	5599	531	206	493	922	52	73	12			3 RC building major 2 RC minor		
17	Tanahau	553	2952	84570	1455	8862	171	194	335	386	5	2	2	Major damage				
18	Kaski	430	2726	86559	1170	4468	101	69	161	434	11	5						
19	Rupendeahi	414	2901	198789	1394	6039	80	244		257	3	2	6	Crack		1 RC Building crack, 2 hostel		
20	Baglung	589	2528	86204	1461	5428	174	70	189	267			2	Normal				
21	Taplejung	336	1603	61033	770	3395	33	45	14	42	1							
22	Panchthar	390	1862	63460	1140	4254	173	37	250	236	12							
23	Ilam	440	2313	65703	1436	4622	43	65	69		3							
24	Morang	547	4134	197643	1925	7375	70	99			12	25						
25	Dhankuta	315	1570	47386	1220	3392	69	72		180		7						
26	Terhathum	240	1260	31272	834	2560	121	210	167	185	6							
27	Sankhusabha	388	1641	48698	1020	3738	170	135	116	40								
28	Bhojpur	390	1786	55613	1114	3724	120	25			10	3						
29	Solukhumbu	281	1260	37889	786	2645	213	514	365	303	37	2	3			minor damaged		
30	Khotang	501	2098	78074	1343	4767	125	245	51	106	4	1		partially damage		1 RC Building damage		
31	Udayapur	457	2076	98358	1497	5613	175	24	166	501	55	11	1					
32	Pyuthian	360	1511	81417	1122	3799	52	6	71	126	5					1 Rc building damage 1 ECD		
33	Mustang	31	340	2838	186	533	22	58		125	16	12	2					
34	Parbat	320	1981	39328	989	3337	127	170	179	174	1	1				1 RC building minor damage		
35	Manang	32	201	1011	73	240	8	2	1	11							7	
36	Myagdi	269	1246	31156	635	2641	69	69	60	202	4	1						
37	Nawalparasi	518	2947	163014	1954	8687	103	157			2	60						
38	Chitwan	389	2841	114131	1399	4742	160	19	210	373	13	8	2					
39	Palpa	448	2710	80291	1444	5191	43	26	75	120	1	1						
40	Arghakhanchi	406	1985	64207	1040	3925	60	62	129	110	1							
Minor affected District		3917	20279	1281355	11688	43070	246	38	56	173	17	52	1542		45	479		
All Total		19630	104335	4338105	57253	116850	3242	19654	10960	16617	2874	1618	1542		45	479		

Note: Red color: updated today